

# Photo Album for Harris County, TX

Job 19553

October 27, 2007

Your new apparatus is making nice progress. The aerial device is nearing completion of the assembly process and then will be merged with the rest of the truck. Next week the aerial set up work will take place and then the third party aerial test will take place. After this it will be released to the main testing phase where the road test and third party pump test will take place.



DSC07926



DSC07927



DSC07928



DSC07929



DSC07930



DSC07931




DSC07932



DSC07933



DSC07934



DSC07935



DSC07936



DSC07937



DSC07938



DSC07939



DSC07940



DSC07941



DSC07942